



## 18-047



## Army Motor Vehicle Mishap Claims One Soldier's Life

A 20-year-old U.S. Army Reserve Private died 3 March 2018 in an Army motor vehicle mishap at the U.S. Army Reserve Center, Lima, Ohio, at 1300 local. The Soldier became pinned between a stationary vehicle, that he was helping move out of the maintenance bay, and a vehicle driven by another Soldier. He was in battle assembly/drill status at the time of the accident. The USACRC is leading a centralized accident investigation into the mishap.

### ENGAGEMENT TIPS:

Ground guides are required when wheeled and tracked vehicles are backed or when moved within an assembly area or motor pool. Additionally, ground guides are required to be properly trained according to TC 3-21.60, TC 21-305-20, and TC 21-306.

*PLRs provide leaders with awareness of Army loss and highlight potential trends that affect combat readiness. Our Army depends on you to use these PLRs to help Soldiers understand the impact of decisions made on and off duty.*

**PRINT IT**

Additional U.S. Army Combat Readiness Center PLR resources can be found on the USACRC website at <https://safety.army.mil/PLR>.

