

## PLR ARMY PRELIMINARY LOSS REPORT

18-082



A 21-year-old Specialist assigned to 75th Field Artillery Brigade, Fort Sill, Oklahoma, died in an Army combat vehicle mishap 13 July 2018 on the installation at 1330 local. The Soldier was ground guiding an M270 MLRS when he was pinned between it and another M270.

## **ENGAGEMENT TIPS:**

- Ground guides should never position themselves directly in front of or behind the vehicle they are ground guiding.
- Operators should stop the vehicle immediately if they lose sight of the ground guide.
- For more tips and information, see <a href="https://safety.army.mil/ON-DUTY/">https://safety.army.mil/ON-DUTY/</a> Government-Motor-Vehicle/Ground-Guiding

PLRs provide leaders with awareness of Army loss and highlight potential trends that affect combat readiness. Our Army depends on you to use these PLRs to help Soldiers understand the impact of decisions made on and off duty.

PRINT IT

Additional U.S. Army Combat Readiness Center PLR resources can be found on the USACRC website at https://safety.army.mil/PLR.





