



22-035



A 23-year-old Specialist assigned to Fort Bragg, North Carolina, died in a GMV mishap 28 April 2022 on the installation, at 1154 local. The Soldier was ejected from an HMMWV that overturned. Three other Soldiers were also ejected and evacuated to a higher-level medical center. Their injuries are currently unknown. Initial reports indicate that the Soldiers were not wearing their seat belts. The mishap is under investigation by the U.S. Army Combat Readiness Center.

Since 2017, the Army has experienced an average of 10 GMV fatalities per year. This was the fourth GMV fatality of FY22 and above the number of GMV fatalities during the same time period last year.

PLRs are intended to be used as an engagement tool for leaders to discuss the hazards and trends impacting Soldier safety and readiness. The PLR contains only basic information but provides sufficient background to allow leaders an opportunity to communicate risk at the Soldier level. More detailed information on this and other Army mishaps can be found on the U.S. Army Combat Readiness Center website at <https://safety.army.mil/lessonslearned>.

To access current U.S. Army accident statistics and reports, visit <https://safety.army.mil/STATISTICS>.

PRINT IT

Additional U.S. Army Combat Readiness Center PLR resources can be found on the USACRC website at <https://safety.army.mil/PLR>.

