



## 18-009



## PMV-2 Mishap Claims One Soldier's Life

A Specialist assigned to 1st Armored Division, Fort Bliss, Texas, died in a PMV-2 mishap 27 October 2017 at 1400 local in Pine Springs, Texas. The Soldier's motorcycle reportedly left the roadway and crashed. He was transported to an area hospital, where he was pronounced dead. The Soldier, who redeployed earlier in the month, was wearing a helmet and had completed required Motorcycle Safety Foundation training seven days prior to the mishap.

*PLRs provide leaders with awareness of Army loss and highlight potential trends that affect combat readiness. Our Army depends on you to use these PLRs to help Soldiers understand the impact of decisions made on and off duty.*

Additional U.S. Army Combat Readiness Center resources can be found on the USACRC website at <https://safety.army.mil>.

**PRINT IT**

**ANALYZE IT**

<https://safety.army.mil/ShrinkLink/163>

**TRAIN IT**

<https://safety.army.mil/ShrinkLink/169>

