



18-041



Maintenance Mishap Claims One Soldier's Life

A Specialist assigned to U.S. Army Special Operations Command, Joint Base Lewis-McChord, Washington, died in a maintenance mishap in the unit motor pool 7 February 2018 at 0645 local. The Soldier was conducting maintenance on an M984 HEMMT wrecker when he reportedly fell from the vehicle while it was in motion and was struck by the rear tires.

PLRs provide leaders with awareness of Army loss and highlight potential trends that affect combat readiness. Our Army depends on you to use these PLRs to help Soldiers understand the impact of decisions made on and off duty.

PRINT IT

Additional U.S. Army Combat Readiness Center PLR resources can be found on the USACRC website at <https://safety.army.mil/PLR>.

