



18-103



ACV Mishap Claims One Soldier's Life

A First Lieutenant assigned to 75th Ranger Regiment, Fort Benning, Georgia, died in an Army combat vehicle mishap 7 September 2018 at 2141 local. The Soldier was the tank commander of an M-1126 Stryker, supporting live-fire operations on the installation under limited visibility, when the vehicle overturned into a ditch adjacent to the road. He suffered fatal injuries, while the driver and a second Soldier sustained non-fatal injuries. The USACRC is leading a safety investigation into the mishap.

PLRs provide leaders with awareness of Army loss and highlight potential trends that affect combat readiness. Our Army depends on you to use these PLRs to help Soldiers understand the impact of decisions made on and off duty.

PRINT IT

Additional U.S. Army Combat Readiness Center PLR resources can be found on the USACRC website at <https://safety.army.mil/PLR>.

