



## 19-003



## PMV-2 Mishap Claims One Soldier's Life

A 25-year-old Specialist assigned to 36th Engineer Brigade, Fort Hood, Texas, died following a PMV-2 mishap 3 October 2018 in Killeen, Texas, at 1730 local. The Soldier was reportedly thrown from his motorcycle after he lost control and struck a street light pole. He was airlifted to a local hospital, where he died nine days later following removal from life support. The Soldier was wearing personal protective equipment but had yet to complete the Motorcycle Safety Foundation's Basic RiderCourse.

*PLRs provide leaders with awareness of Army loss and highlight potential trends that affect combat readiness. Our Army depends on you to use these PLRs to help Soldiers understand the impact of decisions made on and off duty.*

PRINT IT

Additional U.S. Army Combat Readiness Center PLR resources can be found on the USACRC website at <https://safety.army.mil/PLR>.

