




22-073



A Private First Class assigned to Fort Bliss, Texas died in a PMV-4 mishap 28 Aug 2022 in El Paso, Texas, at 2230 local. The Soldier's vehicle struck a concrete barrier at a high rate of speed and caught fire, resulting in the remains of the Soldier being unrecognizable. It is unknown if alcohol was involved. This mishap is currently under investigation by local law enforcement.

Since 2017, the Army has lost an average of 35 Soldiers a year to PMV-4 mishaps. This mishap was the 28th PMV-4 fatality of FY22 and below the number of fatalities for the same time period last year.

PLRs are intended to be used as an engagement tool for leaders to discuss the hazards and trends impacting Soldier safety and readiness. The PLR contains only basic information but provides sufficient background to allow leaders an opportunity to communicate risk at the Soldier level. More detailed information on this and other Army mishaps can be found on the U.S. Army Combat Readiness Center website at <https://safety.army.mil/lessonslearned>.

To access current U.S. Army accident statistics and reports, visit <https://safety.army.mil/STATISTICS>.

PRINT IT

Additional U.S. Army Combat Readiness Center PLR resources can be found on the USACRC website at <https://safety.army.mil/PLR>.

