




23-002



A 23-year-old Specialist assigned to Fort Bliss, Texas, died in a PMV-4 mishap 10 October 2022 in Junction, Texas, at 1859 local. Reportedly, the Soldier was traveling on I-10 in a Ford F150 and had an accident at mile-marker 116. He was pronounced dead at the scene. The specific circumstances of the mishap, including speed, the Soldier's use of seat belt, and the involvement of alcohol or drugs as contributing factors, are currently unknown. The unit/safety points of contact are awaiting further documentation and updates from the investigation.

Since FY18, the Army has lost an average of 35 Soldiers a year to PMV-4 mishaps. This mishap was the first PMV-4 fatality of FY23 and above the number of fatalities for the same time period last year.

PLRs are intended to be used as an engagement tool for leaders to discuss the hazards and trends impacting Soldier safety and readiness. The PLR contains only basic information but provides sufficient background to allow leaders an opportunity to communicate risk at the Soldier level. More detailed information on this and other Army mishaps can be found on the U.S. Army Combat Readiness Center website at <https://safety.army.mil/lessonslearned>.

To access current U.S. Army accident statistics and reports, visit <https://safety.army.mil/STATISTICS>.

PRINT IT

Additional U.S. Army Combat Readiness Center PLR resources can be found on the USACRC website at <https://safety.army.mil/PLR>.

